Oil Field Environmental Incident Summary

Responsible Party: MBI

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: FEDERAL 10-1

Field Name: BUCKHORN Well File #: 8874

Date Incident:6/26/2014Time Incident:14:30Facility ID Number:County:BILLINGSTwp:144Rng:102Sec:10Qtr:

Location Description:

Submitted By: Nathan Ehlis Received By:

Contact Person: Rafe Espinoza

1700 BROADWAY STE 2300

DENVER, CO 80290

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 60 Barrels 58 Barrels 60 barrels

Other

Description of Other Released Contaminant:

Just production water only, no other type of release

Inspected: Written Report Received: 1/7/2016 Clean Up Concluded: 10/1/2014

Risk Evaluation:

Risks are minimal to zero, because the spill was contained inside of the berm.

Areal Extent:

All of the spill was contained inside of the berm

Potential Environmental Impacts:

Risks are minimal to zero, because the spill was contained inside of the berm.

Action Taken or Planned:

The spill was completely contained in the berm. all of the fluids were sucked up and taken to the Knudson SWD for disposal. the berm will then be dug up and replaced, all of the dirty berm material will be take to the MBI Knudson SWD for disposal.

Wastes Disposal Location: All of the Production water as well as the berm material will be take to MBI's Knudson SWD

Agencies Involved:

Updates

Date: 6/27/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location within the diking, according to the report. NDIC retains oversight.